Going Online with an NX-SL Safety CPU Unit

| Steps |
|---|
| ① Go online with the Controller.
② In the "Connect to Safety CPU Unit" dialog box, select [OK]. |

Detailed Steps

① Go online with the Controller.
Go online with the Controller by referring to "**Going Online with an NJ/NX Controller**".

*You can go online from the safety project if the Controller is in a state it can go online.

② In the "Connect to Safety CPU Unit" dialog box, select [OK].


* With the Sysmac Studio Ver. 1.49 and higher versions, the dialog box shown below will appear before the above dialog box, select the [Yes] button to proceed.

If the checkmark in the red frame in the figure below is unchecked in the safety options settings, monitoring will not begin even when online.

You can start monitoring the safety application by selecting the icon button shown in the red frame in the figure below in the safety project.